

Appendix D

Exploration Photographs

CONTENTS

- Figure D-1, Exploration Photographs, Borings SW-B-01 and SW-B-02
- Figure D-2, Exploration Photographs, Borings SW-B-03 and SW-B-04
- Figure D-3, Exploration Photographs, Borings SW-B-05 and SW-B-06
- Figure D-4, Exploration Photographs, Borings SW-B-07 and SW-B-08
- Figure D-5, Exploration Photographs, Borings SW-B-09 and SW-B-10
- Figure D-6, Exploration Photographs, Borings SW-B-11 and SW-B-12
- Figure D-7, Exploration Photographs, Borings SW-B-13 and SW-B-14
- Figure D-8, Exploration Photographs, Borings SW-B-15 and SW-B-16
- Figure D-9, Exploration Photographs, Borings SW-B-17 and SW-B-18
- Figure D-10, Exploration Photographs, Borings SW-B-19 and SW-B-20
- Figure D-11, Exploration Photographs, Borings SW-B-21 and SW-B-22
- Figure D-12, Exploration Photographs, Borings SW-B-23 and SW-B-24
- Figure D-13, Exploration Photographs, Borings SW-B-25 and SW-B-26
- Figure D-14, Exploration Photographs, Borings SW-B-27 and SW-B-28
- Figure D-15, Exploration Photographs, Borings SW-B-29 and SW-B-30
- Figure D-16, Exploration Photographs, Borings SW-B-31 and SW-B-32
- Figure D-17, Exploration Photographs, Borings SW-B-33 and SW-B-34
- Figure D-18, Exploration Photographs, Borings SW-B-35 and SW-B-36
- Figure D-19, Exploration Photographs, Borings SW-B-37 and SW-B-38
- Figure D-20, Exploration Photographs, Borings SW-B-39 and SW-B-40
- Figure D-21, Exploration Photographs, Borings SW-B-41 and SW-B-42
- Figure D-22, Exploration Photographs, Boring SW-B-43 and Test Pit TP-1
- Figure D-23, Exploration Photographs, Test Pits TP-2 and TP-3
- Figure D-24, Exploration Photographs, Test Pits TP-4 and TP-5
- Figure D-25, Exploration Photographs, Test Pits TP-6 and TP-7
- Figure D-26, Exploration Photographs, Test Pit TP-8 and Boring SW-B-44

APPENDIX D: EXPLORATION PHOTOGRAPHS

- Figure D-27, Exploration Photographs, Borings SW-B-45 and SW-B-46
- Figure D-28, Exploration Photographs, Borings SW-B-47 and SW-B-48
- Figure D-29, Exploration Photographs, Borings SW-B-49 and SW-B-50
- Figure D-30, Exploration Photographs, Boring SW-B-51



Photograph 1 - boring SW-B-01 during drilling.



Photograph 2 - boring SW-B-02 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-01 AND SW-B-02**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-1
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 3. Boring SW-B-03 during drilling.



Photograph 4. Boring SW-B-04 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-03 AND SW-B-04**

January 2021

100062-003



Photograph 5. Boring SW-B-05 during drilling.



Photograph 6. Boring SW-B-06 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-05 AND SW-B-06**

January 2021

100062-003



Photograph 7. Boring SW-B-07 after drilling.



Photograph 8. Boring SW-B-08 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-07 AND SW-B-08**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-4
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 9. Boring SW-B-09 during drilling.



Photograph 10. Boring SW-B-10 before drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-09 AND SW-B-10**

January 2021

100062-003



Photograph 11. Boring SW-B-11 during drilling.



Photograph 12. Boring SW-B-12 after drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-11 AND SW-B-12**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-6
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 13. Boring SW-B-13 during drilling.



Photograph 14. Boring SW-B-14 before drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-13 AND SW-B-14**

January 2021

100062-003



Photograph 15. Boring SW-B-15 during drilling.



Photograph 16. Boring SW-B-16 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-15 AND SW-B-16**

January 2021

100062-003



Photograph 17. Boring SW-B-17 during drilling.



Photograph 18. Boring SW-B-18 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-17 AND SW-B-18**

January 2021

100062-003

SHANNON & WILSON, INC.
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS FIG. D-9



Photograph 19. Boring SW-B-19 during drilling.



Photograph 20. Boring SW-B-20 before drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-19 AND SW-B-20**

January 2021

100062-003

SHANNON & WILSON, INC.
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS FIG. D-10



Photograph 21. Boring SW-B-21 before drilling.



Photograph 22. Boring SW-B-22 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-21 AND SW-B-22**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-11
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 23. Boring SW-B-23 during drilling.



Photograph 24. Boring SW-B-24 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-23 AND SW-B-24**

January 2021

100062-003



Photograph 25. Boring SW-B-25 during drilling.



Photograph 26. Boring SW-B-26 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-25 AND SW-B-26**

January 2021

100062-003



Photograph 27. Boring SW-B-27 during drilling.



Photograph 28. Boring SW-B-28 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-27 AND SW-B-28**

January 2021

100062-003



Photograph 29. Boring SW-B-29 during drilling.



Photograph 30. Boring SW-B-30 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-29 AND SW-B-30**

January 2021

100062-003



Photograph 31. Boring SW-B-31 during drilling.



Photograph 32. Boring SW-B-32 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-31 AND SW-B-32**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-16
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 33. Boring SW-B-33 during drilling.



Photograph 34. Boring SW-B-34 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-33 AND SW-B-34**

January 2021

100062-003



Photograph 35. Boring SW-B-35 during drilling.



Photograph 36. Boring SW-B-36 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-35 AND SW-B-36**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-18
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 37. Boring SW-B-37 during drilling.



Photograph 38. Boring SW-B-38 after drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-37 AND SW-B-38**

January 2021

100062-003



Photograph 39. Boring SW-B-39 during drilling.



Photograph 40. Boring SW-B-40 after drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-39 AND SW-B-40**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-20
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 41. Boring SW-B-41 during drilling.



Photograph 42. Boring SW-B-42 after drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-41 AND SW-B-42**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-21
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 43. Boring SW-B-43 during drilling.



Photograph 44. Test Pit TP-1 during excavation.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-43 AND TEST PIT TP-1**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-22
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 45. Test Pit TP-2 during excavation.



Photograph 46. Test Pit TP-3 during excavation.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
TEST PITS TP-2 AND TP-3**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-23
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 47. Test Pit TP-4 during excavation.



Photograph 48. Test Pit TP-5 during excavation.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
TEST PITS TP-4 AND TP-5**

January 2021

100062-003



Photograph 49. Test Pit TP-6 during excavation.



Photograph 50. Test Pit TP-7 during excavation.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
TEST PITS TP-6 AND TP-7**

January 2021

100062-003



Photograph 51. Test Pit TP-8 during excavation.



Photograph 52. Boring SW-B-44 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
TEST PIT TP-8 AND BORING SW-B-44**

January 2021

100062-003



Photograph 53. Boring SW-B-45 during drilling.



Photograph 54. Boring SW-B-46 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-45 AND SW-B-46**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-27
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 55. Boring SW-B-47 during drilling.



Photograph 56. Boring SW-B-48 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-47 AND SW-B-48**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-28
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 57. Boring SW-B-49 during drilling.



Photograph 58. Boring SW-B-50 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORINGS SW-B-49 AND SW-B-50**

January 2021

100062-003

SHANNON & WILSON, INC. FIG. D-29
GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Photograph 59. Boring SW-B-51 during drilling.

Reds Meadow Road Improvements
FTFS 03S11(1)
Madera County, California

**EXPLORATION PHOTOGRAPHS,
BORING SW-B-51**

January 2021

100062-003